


$$\frac{V}{\cos(\phi - \alpha)} = \frac{V_s}{\cos \alpha} = \frac{V_c}{\sin \phi}$$


Cutting Forces

R resultant



(a)

F friction
 N normal force
 F_s shear
 F_n normal



(b)

$$F_s = R \cos(\phi + \beta - \alpha)$$

F_t thrust
 F_c cutting

$$F = R \sin \beta$$

$$N = R \cos \beta$$

$$F_s = F_c \cos \phi - F_t \sin \phi$$

$$F_u = F_c \sin \phi + F_t \cos \phi$$

$$\mu = \frac{F}{N} = \frac{F_t + F_c \tan \alpha}{F_c - F_t \tan \alpha}$$

$$F_t = R \sin(\beta - \alpha)$$

$$F_t = F_c \tan(\beta - \alpha)$$

Power $F_c V$

Shearing Power $F_s V_s$

Friction Power $F V_c$

Specific Energy

Shearing

$$u_s = \frac{F_s V_s}{w t_0 V}$$

$$u_t = u_s + u_f$$

Friction

$$u_f = \frac{F V_c}{w t_0 V} = \frac{F_r}{w t_0}$$

Material	Specific energy W-s/mm³
Aluminum alloys	0.4–1
Cast irons	1.1–5.4
Copper alloys	1.4–3.2
High-temperature alloys	3.2–8
Magnesium alloys	0.3–0.6
Nickel alloys	4.8–6.7
Refractory alloys	3–9
Stainless steels	2–5
Steels	2–9
Titanium alloys	2–5

Example

Friction $\mu = 0.25$

Width $w = 6 \text{ mm}$ $\frac{1}{4} \text{ in}$

cut depth $t_0 = 0.2 \text{ mm}$ 0.008 in

cutting speed $V = 0.12 \text{ m/s}$ 23 fpm

rake $\alpha = 10^\circ$

Steel specific energy $u_t = 5 \frac{\text{W s}}{\text{mm}^3}$

$$u_t = u_s + u_f$$

$$5 = \frac{F_s V_s}{w t_0 V} + \frac{F_r}{w t_0}$$

$$5 = \frac{F_s \cancel{V} \cos \alpha}{w t_0 \cancel{V} \cos(\phi - \alpha)} + \frac{F_r}{w t_0}$$

$$\beta = \tan^{-1}(\mu) = \tan^{-1}(0.25) = 14^\circ$$

$$\phi = 45^\circ + \frac{\alpha}{2} - \frac{\beta}{2} = 45^\circ + \frac{10^\circ}{2} - \frac{14^\circ}{2} = 43^\circ$$

$$r = \frac{t_0}{t_c} \quad r = \frac{\sin \phi}{\cos(\phi - \alpha)} = 0.21$$

$$t_c = \frac{t_0}{r} = \frac{0.2 \text{ mm}}{0.21} = 0.25 \text{ mm}$$

$$\begin{aligned}
 S &= \frac{F_s \cos \alpha}{w t_0 \cos(\beta - \alpha)} + \frac{F_r}{w t_c} \\
 &= \frac{F_s \cos \alpha}{w t_0 \cos(\beta - \alpha)} + \frac{F \cancel{t_0}}{w \cancel{t_0} t_c} \\
 &= \frac{F_s \cos \alpha}{w t_0 \cos(\beta - \alpha)} + \frac{R \sin \beta}{w t_c} \\
 &= \frac{R \cos(\beta + \beta - \alpha) \cos \alpha}{w t_0 \cos(\beta - \alpha)} + \frac{R \sin \beta}{w t_c}
 \end{aligned}$$

$$S = R \frac{0.67}{0.39 w t_0} + R \frac{0.29}{w t_c}$$

$$\frac{S}{\frac{0.67}{0.39 w t_0} + \frac{0.29}{w t_c}} = R$$

$$\frac{S \frac{W S}{\text{mm}^3}}{\frac{0.8}{6 \text{ mm } 0.2 \text{ mm}} + \frac{0.24}{6 \text{ mm } 0.25 \text{ mm}}} = R$$

$$R = 6 \frac{W S}{\text{mm}}$$

$$6 \frac{\cancel{\text{W}}/\cancel{\text{s}}}{\cancel{\text{mm}}} \frac{1 \frac{\text{kg m}^2}{\text{s}^2}}{1 \cancel{\text{W}}} \frac{1000 \cancel{\text{mm}}}{1 \text{ m}} = 6000 \frac{\text{kg m}}{\text{s}^2}$$

$$= 6 \text{ kN} \quad \approx 1350 \text{ lb}$$

$$F_c = R \cos(\beta - \alpha) = 6 \text{ kN} \cos(14^\circ - 13^\circ) \approx 6 \text{ kN}$$

Power $6 \text{ kN} \cdot 0.12 \frac{\text{m}}{\text{s}} = 721 \text{ W}$
 $\approx 1 \text{ hp}$

Temperature in cutting

metallurgy of tool and workpiece

fire danger

thermal expansion

workpiece

tool

softens

$$T_{\text{mean}} \propto V^a f^b$$

V cutting speed

f feed rate

Carbide


$$a = 0.2$$


$$b = 0.125$$

high speed
steel






$$a = 0.5$$

$$b = 0.375$$





Tool Wear



Taylor tool

life equation

$$VT^n = C$$


V cutting speed

T time

n }
C }
exponent
constant


} depend on
tool/material





		Hardness (HB)	Ferrite	Pearlite
①	As cast	265	20%	80%
②	As cast	215	40	60
③	As cast	207	60	40
④	Annealed	183	97	3
⑤	Annealed	170	100	—

Ductile Iron



Optimal Cutting Speed

Tool wear lower cutting speed better

Cycle time faster cutting speed better

Tool cost tool replacement time

Machine time Deadline