



$$\frac{V}{\cos(\phi - \alpha)} = \frac{V_s}{\cos \alpha} = \frac{V_c}{\sin \phi}$$




$$V_s = \frac{V \cos \alpha}{\cos(\phi - \alpha)}$$

Cutting Forces



(a)

F friction
 N normal



(b)

$$F_s = R \cos(\phi + \beta - \alpha)$$

$$F = R \sin \beta$$

$$N = R \cos \beta$$

$$F_s = F_c \cos \phi - F_t \sin \phi$$

$$F_n = F_c \sin \phi + F_t \cos \phi$$

$$F_t = R \sin(\beta - \alpha)$$

$$F_c = F_t \tan(\beta - \alpha)$$

$$\mu = \frac{F}{N} = \frac{F_t + F_c \tan \alpha}{F_c - F_t \tan \alpha}$$

Total Power $F_c V$

Shearing power $F_s V_s$

Friction power $F V_c$

Specific energy

Shear $u_s = \frac{F_s V_s}{w t_0 V}$

Friction $u_f = \frac{F V_c}{w t_0 V} = \frac{F_c}{w t_0}$

Total $u_t = u_s + u_f$

| Material | Specific energy W-s/mm³ |
|-------------------------|---|
| Aluminum alloys | 0.4–1 |
| Cast irons | 1.1–5.4 |
| Copper alloys | 1.4–3.2 |
| High-temperature alloys | 3.2–8 |
| Magnesium alloys | 0.3–0.6 |
| Nickel alloys | 4.8–6.7 |
| Refractory alloys | 3–9 |
| Stainless steels | 2–5 |
| Steels | 2–9 |
| Titanium alloys | 2–5 |

Example

Friction $\mu = 0.25$

chip width $w = 6 \text{ mm}$

cut depth $t_0 = 0.2 \text{ mm}$

cutting speed $V = 0.12 \text{ m/s}$

$\frac{1}{4}$ in

0.008 in

23 rpm

steel specific energy $u_t = 5 \frac{\text{W}}{\text{mm}^3}$

rake angle $\alpha = 10^\circ$

find R and Power

$$r = \frac{t_0}{t_c} \quad t_c = \frac{t_0}{r} = \frac{0.2 \text{ mm}}{0.81} = 0.25 \text{ mm}$$

$$u_t = u_s + u_f$$

$$5 = \frac{F_s V_s}{w t_0 V} + \frac{F_r}{w t_0}$$

$$= \frac{F_s V_s}{w t_0 V} + \frac{r \cancel{t_0}}{w \cancel{t_0} t_c}$$

$$= \frac{F_s V \cos \alpha}{w t_0 V \cos(\phi - \alpha)} + \frac{F}{w t_c}$$

$$\beta = \tan^{-1}(\mu) = 19^\circ$$

$$\phi = 45^\circ + \frac{\alpha}{2} - \frac{\beta}{2} = 45 + \frac{10}{2} - \frac{19}{2} = 43^\circ$$

$$r = \frac{\sin \phi}{\cos(\phi - \alpha)} = 0.81$$

$$S = \frac{F_s \cos \alpha}{w t_o \cos(\beta - \alpha)} + \frac{F}{w t_c}$$

$$S = \frac{F_s \cos \alpha}{w t_o \cos(\beta - \alpha)} + \frac{R \sin \beta}{w t_c}$$

$$S = \frac{R \cos(\beta + \alpha - \alpha) \cos \alpha}{w t_o \cos(\beta - \alpha)} + \frac{R \sin \beta}{w t_c}$$

$$S = R \left(\frac{0.3}{w t_o} + \frac{0.29}{w t_c} \right)$$

$$\frac{S}{\frac{0.3}{w t_o} + \frac{0.29}{w t_c}} = R$$

$$\frac{0.3}{w t_o} + \frac{0.29}{w t_c}$$

$$\frac{S \frac{w s}{\text{mm}}}{\frac{0.3}{6 \text{ mm} \cdot 0.2 \text{ mm}} + \frac{0.29}{6 \text{ mm} \cdot 0.25 \text{ mm}}} = 6 \frac{w s}{\text{mm}}$$

$$\frac{0.3}{6 \text{ mm} \cdot 0.2 \text{ mm}} + \frac{0.29}{6 \text{ mm} \cdot 0.25 \text{ mm}}$$

$$6 \frac{w s}{\text{mm}} \frac{1 \text{ kg m}^2 / \text{s}^2}{1 \cancel{\text{kg}}} \frac{1000 \cancel{\text{mm}}}{1 \cancel{\text{m}}} = 6000 \frac{\text{kg m}}{\text{s}^2}$$

$$= 6 \text{ kN}$$

$$\approx 1350 \text{ lb}$$

Power $F_c V = 6 \text{ kN} \cdot 0.12 \text{ m/s} = 721 \text{ W} \approx 1 \text{ hp}$

$$F_c = R \cos(\beta - \alpha) = 6 \text{ kN} \cos(14 - 10) = 6 \text{ kN}$$

Temperature in cutting

Material softness

Tool softness

Material change

Melt

Fire Danger

Thermal expansion

$$T_{\text{mean}} \propto V^a f^b$$


V cutting speed
 f feed rate


Carbide

$$a = 0.2$$
$$b = 0.125$$

high speed
steel

$$a = 0.5$$
$$b = 0.375$$










Tool Wear

Taylor tool life equation


$$VT^n = C$$

V cutting speed
 T time to replacement
 n exponent
 C constant

} depend on tool/material








| | Hardness (HB) | Ferrite | Pearlite |
|------------|---------------|---------|----------|
| ① As cast | 265 | 20% | 80% |
| ② As cast | 215 | 40 | 60 |
| ③ As cast | 207 | 60 | 40 |
| ④ Annealed | 183 | 97 | 3 |
| ⑤ Annealed | 170 | 100 | — |

Ductile Iron



Optimal

Cutting speed

Tool life

Lower is better

Cycle times

Higher is better

Tool cost

Tool replacement time

Deadline