

3D printing

Additive Manufacturing

CAD → Processing → 3D printer

Machining Subtractive Manufacturing

Slow

FDM

Plastic Fused Deposition Modelling
MultiJet Printing

UV

curable resin

SLA

Stereolithography

SLS

Selective laser sintering

SLS

Plastic

Laser

Aluminium

Laser

Titanium




Electron Beam

Binder Jetting


Ceramics

Process	Supply phase	Layer creation technique	Type of phase change	Materials
Stereolithography	Liquid	Liquid layer curing	Photopolymerization	Photopolymers (acrylates, epoxies, colorable resins, and filled resins)
CLIP	Liquid	Liquid layer curing	Photopolymerization	Similar to stereolithography
Multijet/PolyJet	Liquid	Liquid layer curing	Photopolymerization	similar to stereolithography
Material jetting	Liquid	Droplet deposition	Solidification	Polymers and wax
Fused-deposition modeling	Solid	Extrusion of melted polymer	Solidification	Thermoplastics such as ABS, polycarbonate, and polysulfone
Binder jetting	Powder	Binder-droplet deposition onto powder layer	No phase change	Ceramic, polymer, or metal powder; sand
Selective laser sintering	Powder	Layer of powder	Sintering	Polymer powder such as nylon
Selective Laser melting	Powder	Layer of powder	Solidification	Metal powders such as stainless steel, titanium, copper, and aluminum
Electron-beam melting	Powder	Layer of powder	Solidification	Titanium and titanium alloys, cobalt chrome
Laminated-object manufacturing	Solid	Deposition of sheet material	No phase change	Paper and polymers
Laser-engineered net shaping	Powder	Injection of powder stream	Solidification	Titanium, stainless steel, aluminum

FDM




(a)



(b)


layer thickness
0.01"



(c)




(d)





SLA

Upside down




SLA







SLS



Subtractive
Manufacturing



(a)



(b)

FEA

Finite elements
analysis

Additive
Manufacturing



(c)

Topology

Optimization



Aerospace



- ▶ FDM (<https://youtu.be/AW-8EVRI5H8>)
- ▶ FDM Close Up (<https://youtu.be/uwpmOKgtZEQ>)
- ▶ SLA (https://youtu.be/n_muoxfXIEg)
- ▶ SLS (<https://youtu.be/9l354lmxazs>)
- ▶ Material Jetting (<https://youtu.be/oi0JEhGqTuU>)
- ▶ Electron Beam Melting (<https://youtu.be/jqjD-FWMexo>)
- ▶ Topology Optimization (<https://hackaday.com/2019/08/02/computer-optimized-3d-printed-bookshelves/>)
- ▶ Concrete 3D Printing
(<https://www.tiktok.com/@ericmartinmoney/video/7056279651836022062>)
- ▶ Press Brake
(<https://www.tiktok.com/@kukamachina/video/7152516763983416619>)
- ▶ Centrifugal Casting
(<https://www.tiktok.com/@lukas.thasme/video/7154585293696290053>)
- ▶ Something Scarry
(<https://www.tiktok.com/@wdrcnctools/video/7154741091177123114>)

Gap bed Lathe

